

Unannounced Variation Application Premises Inspection Report

29 October 2018











Magherafelt Manor ID:11933

Variation Reference VA010965

Type of service: Nursing Home

Address: 22 Pound Road, Magherafelt, BT45 6NR

Tel No: 028 79300284 Inspector: Raymond Sayers It should be noted that this inspection report should not be regarded as a comprehensive review of all strengths and areas for improvement that exist in the service. The findings reported on are those which came to the attention of RQIA during the course of this inspection. The findings contained within this report do not exempt the service from their responsibility for maintaining compliance with legislation, standards and best practice.

1.0 What we look for



2.0 Profile of service

This is a nursing home providing care for 34 nursing category patients.

3.0 Service details

Organisation/Registered Provider: Runwood Homes Ltd/ Gavin O`Hare-Connolly	Registered Manager: Siobhan Conway
Person in charge at the time of inspection: Siobhan Conway	Number of registered places: 34

4.0 Inspection summary

An unannounced inspection took place on 29 October 2018 from 13.15 to 13.30.

This inspection was underpinned by:

- The Nursing Homes Regulations (Northern Ireland) 2005
- Department of Health, Social Services and Public Safety (DHSSPS) Care Standards for Nursing Homes, April 2015

The purpose of the inspection was to investigate fire safety issues listed during the evaluation of the variation application ref VA010965 (transfer of Nursing accommodation from first floor to ground floor level, and increasing the number of registered bedrooms by three to 37). It was noted during the examination of the fire alarm zone plans submitted that the fire subcompartment and fire alarm zone boundaries were not in alignment.

The following areas were examined during the inspection:

Fire sub-compartment & fire alarm zone demarcation boundaries.

The findings of this report will provide the provider with the necessary information to assist them to fulfil their responsibilities.

5.0 Inspection outcome

	Regulations	Standards
Total number of areas for improvement	0	1

Areas for improvement and details of the Quality Improvement Plan (QIP) were discussed with Siobhan Conway, Registered Manager, as part of the inspection process. The timescales for completion commence from the date of inspection.

The findings of the inspection were provided to the person in charge at the conclusion of the inspection.

6.0 The inspection

6.1 Fire Safety

Ground Floor Bedrooms: 16 & 17, 18 & 19, 28 & 29 fire alarm activations were identified on the fire panel as in fire zones 5, 7 and 8 respectively, although they were contained within the fire sub-compartment identified with the adjacent communal facility (Lounge, Bath & Salon), designated as fire zone 6.

6.2 Areas for improvement

The facility Fire Safety consultant should be commissioned to undertake a review of the fire alarm system, verifying that modifications to the fire safety controls are compliant with NIHTM84; the fire risk assessment should also be reviewed.

	Regulations	Standards
Total number of areas for improvement	0	1

7.0 Quality improvement plan

Areas for improvement identified during this inspection are detailed in the quality improvement plan (QIP). Details of the QIP were discussed with Siobhan Conway, Registered Manager, as part of the inspection process. The timescales commence from the date of inspection.

The registered provider/manager should note that if the action outlined in the QIP is not taken to comply with regulations and standards this may lead to further enforcement action including possible prosecution for offences. It is the responsibility of the registered provider to ensure that all areas for improvement identified within the QIP are addressed within the specified timescales.

Matters to be addressed as a result of this inspection are set in the context of the current registration of the Nursing Home. The registration is not transferable so that in the event of any future application to alter, extend or to sell the premises RQIA would apply standards current at the time of that application.

7.1 Areas for improvement

Areas for improvement have been identified where action is required to ensure compliance with:

 Department of Health, Social Services and Public Safety (DHSSPS) Care Standards for Nursing Homes, April 2015

7.2 Actions to be taken by the service

The QIP should be completed and detail the actions taken to address the areas for improvement identified. The registered provider should confirm that these actions have been completed and return the completed QIP via Web Portal for assessment by the inspector.

Quality Improvement Plan

Action required to ensure compliance with the Department of Health, Social Services and Public Safety (DHSSPS) Care Standards for Nursing Homes, April 2015

Area for improvement 1

Ref: Standard 48.1,& 48.2

The registered person shall liaise with the facility fire safety consultant plus fire detection & alarm system engineer to ensure that the boundaries of the fire alarm zones and fire safety sub-compartments are in alignment.

Ref: 6.1

Stated: First time

To be completed by: 3 December 2018

Response by registered person detailing the actions taken:

Fire safety consultant and Alarm system engineer have corrected the fire plans and Fire alarm system. The boundries of the fire alarm zones and fire safety sub-compartments are now in alignment.

^{*}Please ensure this document is completed in full and returned via Web Portal*





The Regulation and Quality Improvement Authority
9th Floor
Riverside Tower
5 Lanyon Place
BELFAST
BT1 3BT

Tel 028 9536 1111
Email info@rqia.org.uk
Web www.rqia.org.uk
@RQIANews